

ELASTOMER ENGINEERING

Table of Working Temperature range due to different materials
Tabelle der Arbeitstemperaturen bezogen auf das Material

Material	Minimum	Maximum continuously Dauerbelastung	Maximum at a peak Spitzenbelastung
NPVC/NBR	- 20°C	+ 70°C	+ 80°C
SBR	- 30°C	+ 60°C	+ 70°C
HNBR	- 20°C	+ 125°C	+ 140°C
VAMAC	- 20°C	+ 140°C	+ 160°C